Mini full of holes

Simple job turned big when we discovered a few more holes than expected. Started of as a break issue, the rear wheel cylinders were leaking fluid. But spotted a bit of rust, a poke with a screwdriver and half the car is on the floor.

×

Thats a big hole

- ×
- ×
- ×
- ×
- ×
- ×
- ×